





**Koncovky a spojky typ NA**

Spojka Y		
		
<b>770</b>		
index (POM)	vnitřní průměr hadice [mm]	světlost [mm]
NA-7700000003	3	2,5
NA-7700000004	4	2,5
NA-7700000005	5	3
NA-7700000006	6	4
NA-7700000008	8	5,6
NA-7700000010	10	7
NA-7700000012	12	8,6
NA-7700000013	13	9
NA-7700000014	14	10
NA-7700000016	16	12
NA-7700000019	19	15

Spojka X		
		
<b>772</b>		
index (POM)	vnitřní průměr hadice [mm]	světlost [mm]
NA-7720000004	4	2,9
NA-7720000005	5	3
NA-7720000006	6	4
NA-7720000012	12	8,6

T-kus redukční				
				
<b>761</b>				
index (POM)	vnitřní průměr hadice [mm]			světlost [mm]
	(1)	(2)	(3)	
NA-7618903004	3	4	3	2,5
NA-7618904006	4	6	4	2,7
NA-7618906004	6	4	6	4
NA-7618908004	8	4	8	5,6
NA-7618908006	8	6	8	5,6
NA-7618908012	8	12	8	5,6
NA-7618910006	10	6	10	7
NA-7618910008	10	8	10	7
NA-7618910013	10	13	10	7
NA-7618912006	12	6	12	8,6
NA-7618912008	12	8	12	8,6
NA-7618912010	12	10	12	8,6
NA-7618915006	15	6	15	11
NA-7618915008	15	8	15	11
NA-7618918010	18	10	18	14
NA-7618918015	18	15	18	14

Přímá spojka redukční			
			
<b>751</b>			
index (POM)	vnitř. průměr hadice [mm]	vnitř. průměr hadice [mm]	světlost [mm]
NA-7518904003	4	3	2,5
NA-7518906004	6	4	2,7
NA-7518908004	8	4	2,7
NA-7518908006	8	6	4
NA-7518910006	10	6	4
NA-7518910008	10	8	5,6
NA-7518912008	12	8	5,6
NA-7518912010	12	10	7

